

Reference Number	Title	Description of Goods/Services	Contract Start Date	Contract End Date	Contract Review Date	Department	Deadline for receipt
Q1/201819/1	Box Hall Track Repairs	Repair aggregate track near Castleton				Park Services	23/05/2018
Q1/201819/2	Track Repairs Plum Tree Farm, Danbydale	Drainage & surface improvements				Park Services	23/05/2018
Q1/201819/3	Plum Tree Danbydale	Repairs & extension of rural track	01/09/2018	30/11/2018		Park Services	30/07/2018
Q1/201819/4	Track Repairs Danbydale	Path construction and drainage along a narrow rural track	01/09/2018	30/11/2018		Park Services	30/07/2018
Q1/201819/5	Communications Strategy	Development of a communications strategy				Park Services	04/06/2018
Q1/201819/6	Ryevitalise Landscape Partnership Evaluation Frame	Project evaluation programme & legacy report				Conservation	05/06/2018
Q1/201819/7	Highway Works on A171	Creation of bridleway crossing with holding area				Polyhalite	29/06/2018